



GREG BELL Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA

Division Director

Representatives Present During the Inspection: OGM Pete Hess Environmental Scientist III



Inspection Report

Permit Number:	C0070016
Inspection Type:	COMPLETE
Inspection Date:	Tuesday, June 08, 2010
Start Date/Time:	6/8/2010 12:36:00 PM
End Date/Time:	6/8/2010 1:39:00 PM
Last Inspection:	Thursday, May 13, 2010

Inspector: Pete Hess, Environmental Scientist III

Weather: Mostly clear; a few cumulus clouds. 80s F.

InspectionID Report Number: 2383

Accepted by: jhelfric 6/21/2010

Permitee: MOUNTAIN COAL CO Operator: MOUNTAIN COAL CO

Site: GORDON CREEK 2, 7 & 8 MINES

Address: HC 35 BOX 380, HELPER UT 84526

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: RECLAIMED

Current Acreages

Total Permitted	179.27	
Total Disturbed	34.15	
Phase I	32.52	
Phase II	32.52	
Phase III	0.73	

Mineral Ownership

Types of Operations

✓ Federal ✓ Underground State Surface County ☐ Loadout ✓ Fee Processing Other Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The reclaimed site remains unchanged since the inspection last month. New spring vegetation appears to be doing well.

Inspector's Signature:

Pete Hess, Environmental Scientist III

Date

Tuesday, June

Inspector ID Number: 46

Permit Number: C0070016 Inspection Type: COMPLETE

Inspection Date: Tuesday, June 08, 2010

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	\checkmark		~	
2.	Signs and Markers	✓			
3.	Topsoil		✓		
4.a	Hydrologic Balance: Diversions	✓		✓	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓		✓	
4.c	Hydrologic Balance: Other Sediment Control Measures	✓			
4.d	Hydrologic Balance: Water Monitoring	✓		✓	
4.e	Hydrologic Balance: Effluent Limitations		✓		
5.	Explosives		✓		
6.	Disposal of Excess Spoil, Fills, Benches		V		
7.	Coal Mine Waste, Refuse Piles, Impoundments		✓		
8.	Noncoal Waste	✓			
9.	Protection of Fish, Wildlife and Related Environmental Issues	V		V	
10.	Slides and Other Damage		V		
11.	Contemporaneous Reclamation		✓		
12.	Backfilling And Grading		V		
13.	Revegetation	V		V	
14.	Subsidence Control		V		
15.	Cessation of Operations		V		
16.a	Roads: Construction, Maintenance, Surfacing		V		
16.b	Roads: Drainage Controls		✓		
17.	Other Transportation Facilities		✓		
18.	Support Facilities, Utility Installations		V		
19.	AVS Check	✓			
20.	Air Quality Permit		V		
21.	Bonding and Insurance	✓		V	
22.	Other				

Permit Number: C0070016 Inspection Type: COMPLETE

Inspection Date: Tuesday, June 08, 2010

Page 3 of 3

1. Permits, Change, Transfer, Renewal, Sale

The State issued R645 permit was last renewed in August of 2009 for a five year period.

4.a Hydrologic Balance: Diversions

The reclamation channels at the site remain in a stable condition.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

Jacob's Pond was observed as dry; no compilance issues were identified. The annual impoundment inspection and certification for Jacob's Pond was performed on September 15, 2009, by Dan Guy, P.E., Blackhawk Engineering Company. No compliance issues or safety hazards were observed at that time.

4.d Hydrologic Balance: Water Monitoring

No flow was observed in Bryner Creek. The only water observed was a very minor flow from the spring reporting to the reclamation diversion above Jacob's Pond (mine #8 portal area). All flow was being absorbed into the ground (no water was making it into the pond).

9. Protection of Fish, Wildlife and Related Environmental Issues

One eagle was observed soaring over to the west. No other wildlife was seen at the site.

13. Revegetation

Vegetation at the site appears to be doing well. At this time, there is no sign of vegetation dying from lack of water.

21. Bonding and Insurance

Mountain Coal Company maintains the required general liability insurance through the National Union Fire Insurance Company. The current coverage remains in effect through July 31, 2010. Coverage for damage from the use of explosives is provided, although there are no storage magazines at the site. A surety bond in the amount of \$641,443.00 is guaranteed by the St. Paul Fire and Marine Insurance Company to ensure the remainder of any required reclamation activities at this site. The 3 cell sediment pond at the site was reclaimed in October 2007. To date, no bond release applications for the pond area have been received by the Division. Dr. Patrick Collins of Mt. Nebo Scientific conducted a vegetation survey of the site during 2009. That report was not finalized until after the 2009 Annual Report information had been finalized and submitted to the Division. A second veg survey is to be conducted this year. These are being prepared in anticipation of a bond release application.